



NOTE - IMPROPER SUPPORT OF KEEL FROM AFT END CAN CAUSE FRACTURE OF TAPE BOND AT JOINT AT FRONT OF KEEL

<b>CATALINA YACHTS</b> 21200 VICTORY BLVD. WOODLAND HILLS, CA		
SCALE: NONE	APPROVED BY:	DRAWN BY <i>SD</i>
DATE: 7/28/85		REVISED 5/20/96
<b>KEEL CRACK REPAIR</b>		
		DRAWING NUMBER