


## Catalina 42 Stern Pulpit T1968



All measurements to center of mounting pad on deck.

Note: The mounting pads on your original pulpit were not welded in place using a jig. As a result, the hole pattern in your deck may not match the hole pattern of the new pulpit. The holes in your deck may need to be filled and redrilled.

This is a special order item; your order cannot be cancelled or returned once your order is accepted, so please choose and measure carefully. Complete your order by agreeing to these terms and signing at right.

,	certify that the dimensions of
printed name	

the pulpit and shape and location of the mounting feet as shown in this drawing are correct.

X	Date	
signature		