


## Catalina 350 Stern Pulpit BA9545



All measurements to center of mounting pad on deck.

Note: The mounting pads on your original pulpit were not welded in place using a jig. As a result, the hole pattern in your deck may not match the hole pattern of the new pulpit. The holes in your deck may need to be filled and redrilled.

This is a special order item; your order cannot be cancelled or returned once your order is accepted, so please choose and measure carefully. Complete your order by agreeing to these terms and signing at right.

Ī	certify that the dimensions o
l,	Certify that the differisions of
printed name	<del></del>

the pulpit and shape and location of the mounting feet as shown in this drawing are correct. Note that any changes will result in additional charges due to the complexity of this pulpit.

Κ	Date	
signature		