


Catalina 27 late model Bow Pulpit H2010



All measurements to center of mounting pad on deck.

Note: The mounting pads on your original pulpit were not welded in place using a jig. As a result, the hole pattern in your deck may not match the hole pattern of the new pulpit. The holes in your deck may need to be filled and redrilled. Indexing is available for an additional cost.

This is a special order item; your order cannot be cancelled or returned once your order is accepted, so please choose and measure carefully. Complete your order by agreeing to these terms and signing below.

by agreeing to the	oo terrile and eighing below.
rinted name	certify that the dimensions of
the pulpit and shape and loc in this drawing are correct.	eation of the mounting feet as shown
Xsignature	Date