


An example of an early system with direct overboard discharge of the ice box through a check valve. The check valve was often a problem. The system was later redesigned to include a foot pump and vented loop to eliminate the check valve.

CATALINA YACHTS INC. 21200 VICTORY BLVD. WOODLAND HILLS, CA


PLUMBING SYSTEM

CATALINA 25 OWNERS MANUAL

4,3,1



This system drains the ice box with a foot pump (3) and vented loop (30). It drains overboard through a "T" fitting (33) in the galley sink drain. Although more expensive than the check valve, it is more trouble free and prevents salt water from intruding into the box when the boat heals.



GALLEY SINK AND ICEBOX DRAINS